



# STEPFOUR

Verfahrweg (mm) / Modell:

Xpert 1000 3D	1000 x 1250
Xpert 1800 3D	1800 x 1250
Xpert 2600 3D	2600 x 1250

Hub Z-Achse (mm):

300 oder 500

Vorschub:

Kugelumlaufspindeln

Vorschubantrieb:

Schrittmotoren

Führungssystem:

Patentierte Integralführung  
mit Laufrollen

Wiederholgenauigkeit:

± 0,02 mm

Art des Werkzeugkopfes:

Hochfrequenzspindelsystem

Leistung des Werkzeugkopfes:


bis zu 3 kW/max. 15 kg

Vorschubgeschwindigkeit:


133 mm/s (8000 mm/min)

Automatischer Werkzeugwechsel:

optional bis 10 fach



## Xpert 1000 / 1800 / 2600 3D



**STEP-FOUR GmbH**

Bayernstraße 77 • 5071 Wals-Siezenheim, Austria  
Tel.: ++ 43-(0)662-459378-0 • Fax: ++ 43-(0)662-459378-20  
office@step-four.at • www.step-four.at



# STEPFOUR

Displacement range (mm) / modell:

Xpert 1000 3D	1000 x 1250
Xpert 1800 3D	1800 x 1250
Xpert 2600 3D	2600 x 1250

Lifting height Z-axis (mm):

300 or 500

Work feed:

Ball screw spindles

Work feed drive:

Stepper motors

Repeating accuracy:

± 0,02 mm

Linear guides:

Patented integral guide system  
with track rollers

Kind of spindle system:

High frequency spindles

Max. motor output of the toolhead:

Up to 3 kW/max. 15 kg

Max. feed of work feed:


133 mm/s (8000 mm/min)

Automatic tool changer:

Optional equipment up to 10  
tools



## Xpert 1000 / 1800 / 2600 3D



**STEP-FOUR GmbH**

Bayernstraße 77 • 5071 Wals-Siezenheim, Austria

Tel.: ++ 43-(0)662-459378-0 • Fax: ++ 43-(0)662-459378-20

office@step-four.at • www.step-four.at